31 I-80 Interchange
Poor signage,
No direct interchange

30 Route 28 near I-80 Interchange
No sidewalks

29 Route 28 at US 322
Sharp curve, slow trucks

28 Route 28 near Snyder Road
Sharp curve, narrow lanes

26 Route 28 at Weaver Road
Several vehicle crashes,
Limited access for EMS

27 Route 28 near Seneca Trail
Sharp Curve

24 Route 28 at Cleveland Street
Frequent flooding

25 Route 28 at Moore Road
Poor sight distance

23 Route 28 at Mayport Road
Poor sight distance, truck access issues

20 Route 28 at Penn Street (Redbank Valley School)
Traffic volumes, student safety

19 New Bethlehem Dollar General
Business access issues

18 North Street/West Broad Street
Sharp curve, truck access issues

22 Route 28 near Fishbasket Area
Sharp curve, narrow lanes

21 Route 28 at Redbank Valley Trail Crossing
Visibility and safety of trail users

17 Route 28 at Putneyville Road
Poor intersection sight distance

16 Route 28 near Wadding Road
Vehicle speeds, many curves

15 Route 28 near Deanville Road
Vehicle speeds, poor sight distance

12 Route 28 at West Caldwell Road
Sharp curves, no shoulder

13 Route 28 at Calhoun School Road
Blind intersection

8 Route 28 at Oscar Road
Poor sight distance,
No passing lane

11 Route 28 at Gas Well Road
Blind intersection

7 Route 28 near Ridge Road
No passing lane

10 Route 28 near Goheenville
Vehicle speeds, sharp curves

9 Route 28 at Route 1018
Steep grades, many curves

4 Route 28 at Sloan Hill Road
Poor sight distance

6 Route 28 at Ridge Road
Blind intersection

5 Route 28 near Hankey Lane
No passing lane

3 Route 28 near Anderson Creek Road
Blind intersection, no passing lane

2 Route 28 near Poverty Hill Road
Sharp turns

1 Route 28 at Clearfield Pike
Issues with traffic signal

0 1 2 4 6 8 10
Miles



Route 28 Kittanning to I-80 Regional Corridor Planning Study
Public Survey Concern Locations

Legend

- County Boundary
- Municipal Boundary
- Route 28 Study Corridor
- State Routes
- Public Concern

ROUTE 28 CORRIDOR STUDY
FROM KITTANNING TO I-80